GeneSys
Sensor Systems, Service & Smiles

RELEASE NOTES

08.03.2024: ADMA Data Logger CLI Version 1.0.10.0

- Feature added: New ADMAnet data format version 3.3.5
- Fix: Wrong definition of data format Add-On LatDev version 1.0.0.
- Fix: Deadlog while recorder error.
- Improvement: GUI Layout Update

> **Note**: Suitable for ADMA FW 30.10.x.x (ADMA 3.0 HW) and FW 35.2.x.x (ADMA 3.5 HW).

10.08.2023: ADMA Data Logger CLI Version 1.0.9.8

- Feature added: Add-On Delta 1:5 visualization and logging
- Feature added: Add-On LatDev logging
- Feature added: Target Data logging
- Feature added: Compatible with FW35.1.x.x and FW35.2.x.x JSON formats
- Improvement: Changed default file naming for binary data files
- Improvement: The overview page can be scrolled with the arrow keys if the window size does not provide enough lines
- Improvement: When adding an ADMA, you can use the arrow keys to scroll through default IPs. These can also be edited
- Fix: Program log page can now also be displayed if no ADMA has been configured
- Fix: Automated recording restart fixed

> **Note**: Suitable for ADMA FW 30.10.x.x (ADMA 3.0 HW) and FW 35.1.x.x (ADMA 3.5 HW).

Geschäftsführer / Managing Directors:
Dr. Bertold Huber, David Huber
USt - IdNr.: *DE 178 338 123*

Handelsregister / Commercial Register:
Amtsgericht Freiburg im Breisgau
HRB 471 669

Volksbank Offenburg
IBAN: DE88 6649 0000 0002 7787 00
BIC: GENODE61OG1

Deutsche Bank Filiale Offenburg
IBAN: DE03 6647 0035 0055 8965 00
BIC: DEUTDE6F664

ADMA Data Logger CLI - Release Notes.docx

Seite / Page 1 / 4

01.06.2023: ADMA Data Logger CLI Version 1.0.8.9

- Improvement: GUI Layout Update
- Improvement: Global logfile enabled by default
- Improvement (LINUX): Overall software paths updated to linux standards
- Improvement (LINUX): Replacing special characters in the names of saved files with underscores
- Fix: Performance improvement and fix of memory leaks
- Fix: Continous kalman filter initialization progress visualization
- Fix: The Overall GNSS HW State LED now checks, if the dual antenna function is enabled at menu 6 (ADMA) for indicating a warning of no antenna connection at the secondary antenna interface

Note: Suitable for ADMA FW 30.10.x.x (ADMA 3.0 HW) and FW 35.0.x.x (ADMA3.5 HW).

20.03.2023: ADMA Data Logger CLI Version 1.0.7.0

- Update: Change framework to .NET 6.0
- Fix: Environment paths if the program was started under Linux
- Fix: Access to global log file
- Fix: Display of long program messages

Note: Suitable for ADMA FW 30.10.x.x or older

02.03.2023: ADMA Data Logger CLI Version 1.0.6.0

- Feature: Added program state on main page
- Feature: Added base saving path on main page
- Feature: Added recording state on main page
- Feature: Added scrollable menu ribbon

Note: Suitable for ADMA FW 30.10.x.x or older

03.02.2023: ADMA Data Logger CLI Version 1.0.1.0

- Feature: Automatic restart of data recording is only performed when at least one data packet was received from every connected ADMA before.

GeneSys Elektronik GmbH · In der Spöck 10 · 77656 Offenburg · Germany   +49 (0) 781 96 92 79 – 0   mail@genesys-offenburg.de   www.genesys-offenburg.de

ADMA Data Logger CLI - Release Notes.docx   Seite / Page 2 / 4

- Feature: Data recording can only be started if the configurations of all connected ADMA systems have been loaded successfully.
- Feature: Added menu items to open the location of the measurement data and the configuration file of the ETL CLI.

Note: Suitable for ADMA FW 30.10.x.x or older

01.02.2023: ADMA Data Logger CLI Version 1.0.0.0

- Initial version to support multi ADMA logging.

Note: Suitable for ADMA FW 30.10.x.x or older

GeneSys Elektronik GmbH · In der Spöck 10 · 77656 Offenburg · Germany   +49 (0) 781 96 92 79 – 0   mail@genesys-offenburg.de   www.genesys-offenburg.de

ADMA Data Logger CLI - Release Notes.docx   Seite / Page 3 / 4

Support

Headquarter

GeneSys Elektronik GmbH
In der Spöck 10
77656 Offenburg - Germany

www.genesys-offenburg.de
https://genesys-offenburg.de/support-center/

Phone: +49 (0) 7 81 / 96 92 79- 66
Fax: +49 (0) 7 81 / 96 92 79- 11
E-Mail: support@genesys-offenburg.de

GeneSys Elektronik GmbH · In der Spöck 10 · 77656 Offenburg · Germany   +49 (0) 781 96 92 79 – 0   mail@genesys-offenburg.de   www.genesys-offenburg.de

ADMA Data Logger CLI - Release Notes.docx   Seite / Page 4 / 4