

RELEASE NOTES

29.02.2024: Auxiliary Device Configurator Version 2.4.95

- Reconnect to current IP after reset to default
- Changed behavior and stability when configuring IP
- Updated device firmware
- Optimizations

08.12.2023: Auxiliary Device Configurator Version 2.3.491

- Updated device firmware
- Bugfixes

12.10.2023: Auxiliary Device Configurator Version 2.2.411

- Added IP and subnet mask to configuration

11.09.2023 Auxiliary Device Configurator Version 2.1.371

- Fixed configuration readout error
- Changed default baud rate to 19200
- Performance improvements

10.08.2023: Auxiliary Device Configurator Version 2.0.234

- Initial release version as NTRIP-DGNSS-Box 5 configuration software

SUPPORT

Headquarter

GeneSys Elektronik GmbH
In der Spöck 10
77656 Offenburg - Germany

www.genesys-offenburg.de
<https://genesys-offenburg.de/support-center/>

Phone: +49(0)7 81 / 96 92 79- 66
Fax: +49(0)7 81 / 96 92 79- 11
E-Mail: support@genesys-offenburg.de