

RELEASE NOTES

2024-12-11: Auxiliary Device Configurator Version 2.5.2.1

- Fixed: Added missing entry in service get request

2024-12-02: Auxiliary Device Configurator Version 2.5.2.0

- Fixed: Issue in GPCCA log format parsing
- Changed: Lowest possible configurable recurrence time set to 1 minute

2024-02-29: Auxiliary Device Configurator Version 2.4.95.0

- Fixed: Reconnect to current IP after reset to Default
- Fixed: Behavior and stability when configuring IP
- Fixed: Several optimizations
- Changed: Updated device firmware

2023-12-08: Auxiliary Device Configurator Version 2.3.491.0

- Changed: Updated device firmware
- Fixed: Several minor bugs

2023-10-12: Auxiliary Device Configurator Version 2.2.411.0

- Added: IP and subnet mask configuration

2023-09-11: Auxiliary Device Configurator Version 2.1.371.0

- Fixed: Configuration readout error
- Fixed: Performance issues
- Changed: Default baud rate set to 19200

2023-08-10: Auxiliary Device Configurator Version 2.0.234.0

Note: Initial release version as NTRIP-DGNSS-Box 5 configuration software

SUPPORT

Headquarter

GeneSys Elektronik GmbH
Maria-und-Georg-Dietrich-Str. 6
77652 Offenburg - Germany

www.genesys-offenburg.de
<https://genesys-offenburg.de/support-center/>

Phone: +49(0)7 81 / 96 92 79 - 66
Fax: +49(0)7 81 / 96 92 79 - 11
E-Mail: support@genesys-offenburg.de