

RELEASE NOTES

NTRIP-DGPS BOX 4 CONFIGURATOR

17.03.2022 Version 1.20

Added

- Checking online status of the connection to a cellular provider

Changed

- Added new NTRIP Provider
- Performance improvements

Fixed

- Ping timeout bug
- GNSS Provider URLs

30.11.2021 Version 1.15

Changed

- Unlocked "Device Settings" tab

30.11.2021 Version 1.14

Note

- Updating the software will delete all custom presets. Please export presets before updating and import those afterwards!

Changed

- Removed "auto-detect" baudrate
- Optimized internal settings format

Fixed

- Fixed Preset saving/loading error
- Fixed communication error that caused UI elements to be filled with wrong information
- Fixed login screen forgetting previous login data / license keys

- Fixed mis formatted message boxes
- Fixed errors occurring while setting default settings

30.11.2021 Version 1.10

Added

- Added new icon
- Added option to change baudrate
- Added option to change setting: reopen closed socket

Changed

- Changed name to NTRIP-DGPS Box 4 Configurator
- Changed setting: Reopen closed sockets now on by default (keepopen ON)
- Updated correction data preset list
- Changed message after settings import

Fixed

- Fixed UI errors regarding text highlighting
- Fixed software crash due to incompatible settings versions
- Fixed connection problem causing the software to freeze

GeneSys Elektronik GmbH
In der Spoeck 10
77656 Offenburg - Germany

www.genesys-offenburg.de
www.genesys-adma.de

Phone: +49 (0) 7 81 / 96 92 79- 66
Fax: +49 (0) 7 81 / 96 92 79- 11
eMail: support@genesys-offenburg.de